


FIG. 1
PRIOR ART



15

FIG. 2A
PRIOR ART




FIG. 2B
PRIOR ART




FIG. 3




FIG. 4





FIG. 5



7/13



FIG. 7




FIG. 9B




FIG. 4 is a top-down view of the front of the washing machine 100. The view shows the outer door 450, the inner door 421, and the drum 422. The drum is filled with laundry 430. A detergent dispenser 452 is located on the right side of the door.

FIG. 10

